
## **S-60**

Face mill 60° for cast iron with double sided hexagonal inserts



0.2

.008

0.3

.012


0.4

.016

Feed rate (fn), mm/r, inch/r

Note:

To achieve better surface finish KL geometries can be associated to R/L KW geometry. Wiper inserts must be placed on the insert seat marked with a spot.



0.1

.004

## **General information**

Α

В

С

D



G

Н

AЗ

